




ORBIS


Montage-instructies

1 Place and screw the four hexagonal distancers.






2 Attention!


Place the first cross brace.




3 Place the second cross brace.



4 Place and screw the four steel cable regulators.




5 Place all **Felt elements.**




6 Screw all

» Felt elements to the metal cross structure.



7 Turn off power before installation.



**#We
MakeAn
Impact**